

Economic report

Wind turbines-The cost of a wind turbine is different depending on how much energy you need. Most are around \$10,000-\$20,000. Some people have tried to make their own windmills but most can't handle high wind and don't make a lot of electricity

The workers-This depends on the company, some companies may charge you more than others for labor. It would be best to shop around.

Wind power may be more expensive at first, but it will save you in the long run. Some studies have shown that it would take around 10-15 years to pay it off.

Starting costs for energy resources in dollars

